




P.O. BOX 21595 SARASOTA, FLORIDA 34276-4595
TEL. 888 8ENGAGE >> 941 923 7474 >> FAX. 941 923 5667

ENGAGEAVIATION.COM



AIRCRAFT SALES + MARKETING

Bell 206A-1 (OH-58A)
1971
S/N 41219 (71-20358)
N5092K

NEW GROUND UP REURBISHMENT
FRESH ANNUAL

Experimental Exhibition Category

ACCT: 3440.8

ENGT: 3237.0

Hobbs: 0

COMPONENT

PARTS NUMBER

REMAINING

M/R Head	206-011-100-131	On Condition
T/R YOKE	206-011-819-101	3559.0
Trunnion Assembly	206-011-812-005	Unlimited
M/R BLADE	206-011-250-003	1235.0
M/R BLADE	206-011-250-113	2579.0
M/R GRIP	206-010-102-013	977.0
M/R GRIP	206-010-102-013	670.0
M/R TRUNION	206-011-113-103	3282.0
M/R TT STRAP	206-011-154-105	1032.8
M/R TT STRAP	206-011-154-105	1032.8
M/R PIN	206-010-123-003	360.0

M/R PIN	206-010-123-003	360.0
M/R FITTING	206-011-140-001	360.0
M/R FITTING	206-011-140-001	360.0
M/R Latch Bolt	206-010-169-003	360.0
M/R Latch Bolt	206-010-169-003	360.0
M/R Swashplate	206-010-450-7	On Condition
SWASHPLATE SUPPORT	206-010-452-001	1206.0
COLLECTIVE LEVER	206-010-467-001	1206.0
COLLECTIVE LINK	206-010-407-001	1206.0
SLEEVE	206-010-454-001	1206.0
TUBE	206-001-524-011	1505.0
T/R BLADE	206-016-201-111	740.0
T/R BLADE	206-016-201-111	740.0
K-FLEX	SKCP2348-5	4279.0
Engine	T63-A-700	886.0
T/R Gearbox	206-040-402-3	On Condition

EXTERIOR

NEW AAI RAINGUTTER KIT
NEW UPPER/LOWER WIRE STRIKE KIT WITH LOWER EXTENSION TIP
NEW AAI MAINTENANCE STEPS
GARLICK ENGINE OIL BYPASS REMOVAL KIT
PARTICAL SEPERATOR
FLAP RESTRAINT KIT
AAI MAINTENANCE HANDL

INTERIOR

GARMIN 696 GPS
NEW DAVATRON 800 CLOCK
DUAL CONTROLS
NEW CONCORDE RG-206 LEAD ACID BATTERY

Component Run Sheet is IAW TM55-1520-228-23 Section V Overhaul and Retirement Schedule with is a part of N5092K FAA Approved Maintenance Program. If a component and/or part number is not listed on this sheet it is because it is not applicable to the configuration and/or installation of N5092K. Some Part Numbers reflect the latest Bell Helicopter Applicable part number and/or Overhaul/Retirement Time. This document is subject to current verification; errors may be present. This document is for Reference Only.

